

**NHTSA Recall No 15V537000**

Engine Control Unit Software may cause Low Idle

**Report Receipt Date:** AUG 24, 2015

**NHTSA Campaign Number:** 15V537000

**Component(s):** ELECTRICAL SYSTEM , ENGINE AND ENGINE COOLING

**Potential Number of Units Affected:** 1,060

Vehicle Make	Model	Model Year(s)
BMW	G650GS	2013-2015
BMW	G650GS Sertao	2013-2014

**Manufacturer:** BMW of North America, LLC

**SUMMARY:**

BMW of North America, LLC (BMW) is recalling certain model year 2013-2015 G 650 GS motorcycles manufactured March 8, 2013, to March 2, 2015, and 2013-2014 G 650 GS Sertao motorcycles manufactured March 8, 2013, to May 23, 2014. The affected motorcycles may stall when they are idling and the clutch lever is pulled in.

**CONSEQUENCE:**

If the engine stalls, there is an increased risk of a crash.

**REMEDY:**

BMW will notify owners, and dealers will install a revised version of the engine control unit software, free of charge. The recall is expected to begin October 16, 2015. Owners may contact BMW customer service at 1-800-525-7417 or by email at [CustomerRelations@bmwusa.com](mailto:CustomerRelations@bmwusa.com).

**NOTES:**

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to [www.safercar.gov](http://www.safercar.gov).

Name	Description	Size (kb)
RCAK-15V537-4888.pdf	Recall Acknowledgement	111
RCMN-15V537-9541.pdf	Manufacturer Notices (to Dealers, etc) Stop Sale G650 GS and GS Sertao	11
RCRIT-15V537-5193.pdf	Remedy Instructions and TSB Date: September 2015 Bulletin #: 13 002 15 (023)	874
RCRIT-15V537-9441.pdf	Remedy Instructions and TSB Date: September 2015 Bulletin #: 13 002 15 (023) R	1142