

**Recall ID #54796 - POWER TRAIN:MANUAL TRANSMISSION**

Recall Date

**NOV 27, 2002**

Motorcycle Affected

**2003 BMW R 1150 RS**

Summary

**ON CERTAIN MOTORCYCLES, IT IS POSSIBLE THAT THE 3RD AND 4TH TRANSMISSION GEAR (SHIFT) WHEELS MAY NOT BE SECURELY SEATED ON THE INTERMEDIATE SHAFT. CONSEQUENTLY, WHEN ATTEMPTING TO SHIFT FROM 5TH TO 6TH GEAR, ENGAGEMENT OF THE TWO GEARS MAY OCCUR SIMULTANEOUSLY.**

Consequence

**IF THIS HAPPENS, THE GEAR WHEELS COULD CRACK RESULTING IN A LOSS OF TRANSMISSION CAPABILITY, OR, A LOCK OF TRANSMISSION COULD OCCUR. THE REAR WHEEL COULD LOCK WHICH, DEPENDING UPON TRAFFIC AND ROAD CONDITIONS, AND THE RIDER'S REACTION, COULD AFFECT THE STABILITY OF THE MOTORCYCLE.**

Remedy

**DEALERS WILL INSPECT THE MOTORCYCLES AND REPLACE THE TRANSMISSION GEAR BOX IF NECESSARY. OWNER NOTIFICATION IS EXPECTED TO BEGIN DURING DECEMBER 2002. OWNERS WHO TAKE THEIR VEHICLES TO AN AUTHORIZED DEALER ON AN AGREED UPON SERVICE DATE AND DO NOT RECEIVE THE FREE REMEDY WITHIN A REASONABLE TIME SHOULD CONTACT BMW AT 1-800-831-1117, OPTION #4.**

Potential Motorcycles Affected

**515**

Notes

**BAYERISCHE MOTOREN WERKE**