



# Transport Regulation

[Things You Should Know](#) | [Links](#) | [Contact Us](#)

**Monthly Search:**

## Vehicle Recalls

### Vehicle Recall Search Results for BMW F650 GS, F650 GS Dakar (All year models)

<b>Problem:</b>	Rear brake caliper support bracket	<b>Defect:</b>	Rear brake caliper support bracket bends
<b>Make:</b>	BMW	<b>Consequences:</b>	Caliper contacts the swinging forks at the brake hose connection. This can damage the hose leaking the fluid and cause a loss of the rear brake.
<b>Model:</b>	F650 GS, F650 GS Dakar	<b>Corrective action:</b>	BMW dealers will fit a reinforcing clip or if damaged will replace the rear swinging forks
<b>Variant:</b>		<b>Notif. Date:</b>	9/03/2001
<b>Date Range:</b>	All year models	<b>DOTARS No.:</b>	R01/025
<b>VIN Ranges:</b>	F650 GS: ZE30694 to ZE42484, F650 GS Dakar: ZF60130 to ZF63743	<b>Supplier Name:</b>	BMW
<b>Status:</b>	Inactive	<b>Campaign No.:</b>	00 00 33 08 00